

PPE AND EXPOSURE CONTROL

OVERVIEW

Proper Personal Protective Equipment (PPE) and exposure control protect applicators from chemical hazards, dust, and fumes during resinous coating application.

Requirements

- Respiratory Protection: NIOSH-approved respirators for solvent-borne or dusty operations.
- Skin Protection: Disposable nitrile gloves, long sleeves, pants, and closed toe shoes.
- Eye & Face Protection: Safety goggles or face shields.
- Ventilation: Use forced-air ventilation or extraction systems in enclosed spaces.

Best Practices

- Train all personnel on safe handling and emergency response.
- Inspect PPE before use and replace if damaged.
- Follow SDS guidance for each product.