


For using FR-C10.
Before operating your FR-C10, please read this manual thoroughly and keep it for future reference.

■Features


- Supports the Canon Lens 20Pin.
- Able to be attached to either right or left pan handle of a tripod.

■Parts Names and Functions




■Connection/Use

Connection to Canon Lens



■Outsideview and Dimensions



■Specifications

Input/Output	
HDS connector	6P : for connection to Canon Lens 20Pin
FOCUS switch	Selects the rotating direction of FOCUS Ring
FOCUS ring	Rotating direction is reversible.
General	
Clamp bracket	For fixing FR-C10 on the pan handle of the tripod.
Outside Dimensions	approx. 73 x 73 x 82 mm (main body) (WxHxD)
Weight	approx. 0.5 kg (main body), approx. 0.45 kg (clamp bracket)
Operating Temperature	0 °C ~ 40 °C
Storage Temperature	-20 °C ~ 60 °C
Accessories	
Clamp bracket, 6Pin-20Pin Cable, Operating Instructions	

NOTE Features, design and specifications are subject to change without notice.