






ASSEMBLY INSTRUCTION





(A) x 12  M6x50	(B) x 2  M6x25	(C) x 6  M6x10	(D) x 8  M5x40	(E) x 6  M4x40	(F) x 4  M6x20
(G) x 1  M4	(H) x 1  M3	(I) x 2  M4			


① x1PC



② x2PCS




③ x2PCS



④ x2PCS




⑤ x2PCS



⑥ x2PCS




⑦ x2PCS




⑧ x1PC



⑨ x9PCS




1



(F)	x 4
	
M6x20	


x 2

2





(A)	x 4	(G)	x 1
			
M6x50		M4	

3




(E)	x 6
	
M4x40	

4



(A)	x 8	(G)	x 1
			
M6x50		M4	


5



(C)	x 4	(G)	x 1
 M6x10		 M4	


x 2

6




(C)	x 2	(G)	x 1
 M6x10		 M4	

7






(D)	x 8	(H)	x 1
 M5x40		 M3	

8



(B)	x 2	(G)	x 1
 M6x25		 M4	

9



10

