

111034

1/12HP, 115-60-1, 1.75 AMP, 1725 Motor for a Booster Pump

ITEM NO.	DESCRIPTION	MFG. DATE 3/86 - CURRENT	MFG. DATE 8/83 - 2/86
	MOTOR ID NUMBER	M09181*/M09182**	M09186
	Power Pack	111034	111034
	Motor Bracket (Top)	M61984	M61984
	Motor Bracket (Bottom)	P04244	P04244
	Conduit Box Cover	M61983	M61983
2	End Plate (Shaft End)	M48150	M13414
3	End Plate (Switch End)	M48120	N/A
7	Overload Protector	M48570*/M48450**	N/A
14	Sleeve Bearing (2)	M21240	M21240
9	Centrifugal Switch Assembly	118254	M48182
16	Wicking (2)	M18390	M18390
6	Motor Mount Set	118223	118223
8	Switch Plate Assembly	N/A	M48182
12	Resilient Washer - Buna N (2)	M21750	M21750
11	Washer - Steel (2)	M73060	M73060
13	Washer - Phenolic (2)	M22050	M22050
18	Shim Washer - Mylar (5)	M22080	M22080
15	Cover & Tube	M72555	M72555
19	Oil Retainer (Shaft End)	M21270	M21270
5	Oil Retainer (Switch End)	M21120	M21120

* - Top Lead.

** - Bottom Lead.

N/A - Not Available.

 - Factory recommended spare parts.

Use the list below for cross-reference purposes only. Consult factory if replacement parts are needed for these obsolete motors.

111034 replaces:

MOT101-5

MOT112-5

MOT113-5

MOT132-5


MOT133-5

M09180

NOTE: Refer to page 7 for exploded view of 5" motor.

Five Inch Motor Exploded View 1/12HP, Split Phase Design

PARTS LIST CP-25B-PL (CONTINUED)



- Factory recommended spare parts.