

**ITW-3429**

## FAQ & Photo Guide

3429 Water Cooler Motor Install:

Q: I bought a new 3429 replacement water cooler motor wired it up and it runs, but, does not have enough power to turn the coolant pump?

A: The 3 power cord connections on the new Arc-Zone 3429 motor are NOT the SAME as the OLD MOTOR being replaced.

Customers commonly mix up the RED & White wires when installing to try to make it match the way the old motor was wired. See picture.

