


SECTION 5000- FIXTURE ASSEMBLY

K-20 2 WAY DRAWING (F) ASSEMBLY



1. Empty contents of the K-20 box onto the floor.

2. Cover the base with the outer cover and finish plate.

3. Attach the covered base to the frame with adjustment holes using the attaching bolts.

4. Slide the adjustable arm into place by pressing the adjustment button.