

# SECTION 3000-FIXTURE ASSEMBLY

---

## K41 H-RACK END PANEL ASSEMBLY

Start with:

- Assembled K41 H- Rack
- 2x4 Black Slatgrid
- Grid Hanger
- Tek Screw
- Nut-Driver Bit
- End Cap Bracket

1. Check the rack with a level, and adjust the leveling feet if needed.
2. Measure from the top of the teardrop end down 1". Begin with a grid hanger & a Tek screw.
3. Fasten a grid hanger to each teardrop end using the provided nut driver bit in a power drill or power screwdriver. Steady pressure is needed to drive the screw through metal.
4. Hang the 2x4 Black slatgrid by the fourth square from the top.
5. Place an end spacer on the back of the slatgrid panel up 2 or 3 squares in line with the racks leg. Attach the spacers to the legs of the rack.

# SECTION 3000-FIXTURE ASSEMBLY

## K41 H-RACK END PANEL ASSEMBLY (C)

