


#### For using FR-F10.

Before operating your FR-F10, please read this manual thoroughly and keep it for future reference.

## Features


- Supports the Fujinon Lens 12Pin.
- · Able to be attached to either right or left pan handle of a tripod.

## ■Parts Names and Functions




■Connection/Use

### Connection to Fujinon Lens



# Outsideview and Dimensions





## Specifications

Input/Output	
HDS connector	6P : for connection to Fujinon Lens 1
FOCUS switch	Selects the rotating direction of FOC
FOCUS ring	Rotating direction is reversible.
General	
Clamp bracket	For fixing FR-F10 on the pan handle
Outside Dimensions	approx. 73 x 73 x 82 mm (main body
Weight	approx. 0.5 kg (main body), approx.
Operating Temperature	0 °C ~ 40 °C
Storage Temperature	-20 °C ~ 60 °C
Accessories	
Clamp bracket, 6Pin-12Pin Cable, Operating Instructions	
NOTE Features, design and specifications are su	

12Pin CUS Ring e of the tripod. ly) (WxHxD) . 0.45 kg (clamp bracket)

subject to change without notice.