



TEES *continued*




712
Tee C x C x F – Cast

NOM. SIZE	APPROX. NET WT. LBS.	DIMENSIONS INCHES		
		E	F	G
1/4	0.08	13/16	9/32	9/32
3/8	0.11	11/16	7/16	7/16
3/8 x 3/8 x 1/4	0.12	11/16	7/16	7/16
1/2	0.14	27/32	9/16	9/16
1/2 x 1/2 x 1/4	0.16	13/16	1/2	1/2
1/2 x 1/2 x 3/8	0.15	13/16	1/2	1/2
1/2 x 1/2 x 3/4	0.23	15/16	11/16	11/16
3/4	0.33	1	21/32	21/32
3/4 x 1/2 x 3/4	0.28	1	21/32	11/16
3/4 x 3/4 x 3/8	0.23	7/8	1/2	1/2
3/4 x 3/4 x 1/2	0.24	29/32	9/16	9/16
3/4 x 3/4 x 1	0.40	1 1/8	7/8	7/8
1	0.54	1 1/4	7/8	7/8
1 x 1 x 1/2	0.35	1 1/8	9/16	9/16
1 x 1 x 3/4	0.42	1 3/16	11/16	11/16
1 1/4	0.76	1 7/16	1	1
1 1/4 x 1 1/4 x 1/2	0.49	1 1/4	9/16	9/16
1 1/4 x 1 1/4 x 3/4	0.55	1 5/16	11/16	11/16
1 1/4 x 1 1/4 x 1	0.66	1 7/16	7/8	7/8
1 1/2	1.08	1 5/8	1 1/8	1 1/8
1 1/2 x 1 1/2 x 1/2	0.62	1 3/8	9/16	9/16
1 1/2 x 1 1/2 x 3/4	0.70	1 7/16	11/16	11/16
1 1/2 x 1 1/2 x 1	0.79	1 1/2	13/16	13/16
2	1.74	1 7/8	1 3/8	1 3/8
2 x 2 x 1/2	0.97	1 5/8	17/32	17/32
2 x 2 x 3/4	1.10	1 11/16	11/16	11/16
2 x 2 x 1	1.23	1 3/4	13/16	13/16




712-5
Drop Tee C x C x F – Cast

NOM. SIZE	APPROX. NET WT. LBS.	DIMENSIONS INCHES		
		A	C	E
1/2	0.25	3/8	9/16	7/8
3/4	0.38	1/2	11/16	1



713
Tee C x C x M – Cast



NOM. SIZE	APPROX. NET WT. LBS.	DIMENSIONS INCHES	
		E	F
1/2	0.14	1 3/32	7/16
3/4	0.29	1 9/32	9/16



714
Tee C x F x C – Cast

NOM. SIZE	APPROX. NET WT. LBS.	DIMENSIONS INCHES		
		C	E	S
1/2	0.18	7/16	3/8	7/8
1/2 x 3/4 x 1/2	0.27	7/16	9/16	1 3/16
3/4	0.31	9/16	11/16	1
3/4 x 1/2 x 3/4	0.26	9/16	7/16	15/16
1	0.52	23/32	13/16	1 1/4
1 x 1/2 x 1	0.42	3/4	3/4	1 1/8
1 x 3/4 x 1	0.43	23/32	23/32	1 3/16
1 1/4	0.73	7/8	1	1 13/32
1 1/4 x 1/2 x 1 1/4	0.56	7/8	7/8	1 3/16
1 1/4 x 3/4 x 1 1/4	0.62	7/8	7/8	1 7/32
1 1/2	1.00	1	1 1/8	1 9/16
1 1/2 x 3/4 x 1 1/2	0.88	1	1	1 13/16
2	1.72	1 1/4	1 3/8	1 7/8
2 x 1/2 x 2	1.58	1 1/4	1 1/4	2
2 x 3/4 x 2	1.57	1 1/4	1 1/4	2

TRAPS



698
Suction Line P-Trap
C x C – Wrot

A major application of this fitting is on the suction line of a refrigeration compressor. The line is looped, by use of the Suction Line P-Trap, to the floor prior to being run vertically upwards to prevent the drainage of oil back to the compressor during shut down periods. Additional P-Traps are used for each 20' or riser pipe. this prevents high velocity build-up as the oil or liquid begins to return to the compressor during this shut down period.

NOM. SIZE	APPROX. NET WT. LBS.	DIMENSIONS INCHES			
		C	D	J	K
1/2	0.40	5 3/8	3	3	6
5/8	0.45	5 3/8	2 7/8	3	6
3/4	0.58	5 3/8	2 3/4	3	6
1	0.92	5 1/4	2 21/32	2 31/32	6 3/8
1 1/4	1.51	5 17/32	3 1/32	3 3/4	6 1/4
1 1/2	2.74	7 29/32	3 25/32	5	8 25/32
2	4.05	8 9/32	3 29/32	6	9 13/32

Consult price sheet for Made to Order items and for minimum order quantities.