



SWING CHECK VALVE • 200 PSI BRASS

Item No.	Size	Connection	Inner Qty.	Master Qty.	Each Wt.	
THREADED						
101-001*	1/4"	FPT x FPT	10	100	0.40	• 200 PSI non-shock WOG • Meets NSF 61 requirements • Threaded ends comply with ANSI B1.20.1
101-002*	3/8"	FPT x FPT	10	100	0.40	
101-003*	1/2"	FPT x FPT	10	100	0.40	
101-004*	3/4"	FPT x FPT	5	60	0.53	
101-005*	1"	FPT x FPT	5	40	0.73	
101-006*	1-1/4"	FPT x FPT	5	30	1.28	
101-007*	1-1/2"	FPT x FPT	4	24	1.70	
101-008*	2"	FPT x FPT	2	16	2.62	
101-009*	2-1/2"	FPT x FPT	2	8	4.41	
101-010*	3"	FPT x FPT	1	6	6.78	
101-011*	4"	FPT x FPT	1	3	10.64	
SOLDER						
101-503*	1/2"	C x C	10	100	0.40	• 200 PSI non-shock WOG • Meets NSF 61 requirements • Solder ends comply with ANSI B16.18
101-504*	3/4"	C x C	5	60	0.55	
101-505*	1"	C x C	5	40	0.75	
101-506*	1-1/4"	C x C	5	30	1.28	
101-507*	1-1/2"	C x C	4	24	1.52	
101-508*	2"	C x C	2	16	2.56	
THREADED - NO LEAD						
101-001NL	1/4"	FPT x FPT	10	100	0.4	• 200 PSI WOG • Certified to NSF 61-G • "Lead-Free" Compliant
101-002NL	3/8"	FPT x FPT	10	100	0.4	
101-003NL	1/2"	FPT x FPT	-	15	0.4	
101-004NL	3/4"	FPT x FPT	-	15	0.53	
101-005NL	1"	FPT x FPT	5	40	0.73	
101-006NL	1-1/4"	FPT x FPT	5	30	1.28	
101-007NL	1-1/2"	FPT x FPT	4	24	1.7	
101-008NL	2"	FPT x FPT	2	16	2.62	
SOLDER - NO LEAD						
101-503NL	1/2"	C x C	-	20	0.4	• 200 PSI WOG • Certified to NSF 61-G • "Lead-Free" Compliant
101-504NL	3/4"	C x C	-	20	0.55	
101-505NL	1"	C x C	5	40	0.75	
101-506NL	1-1/4"	C x C	5	30	1.28	
101-507NL	1-1/2"	C x C	4	24	1.52	
101-508NL	2"	C x C	2	16	2.56	

* Please call for availability.