

Sweat Tub Spout Elbow Standard

Tub Spout Elbow

- Male Sweat with Square O Strap with Wall Block Plate –
 Connect tub valve to spout nipple in one easy step
- Male Sweat with Square O Strap with Wall Block Plate –
 1¼" radius fits all valve rough-ins
- Male Sweat with Square O Strap with Wall Block Plate –
 Square O strap and Wall Block are crimped to tube
- MIP Swivel No soldering with easy swivel thread installation
- MIP Swivel 1¼" radius fits all valve rough-ins
- Fixed MIP with Wall Block Plate No soldering with male thread connection
- Fixed MIP with Wall Block Plate 1½" radius fits all valve rough-ins
- FIP Swivel No soldering with easy swivel thread installation
- FIP Swivel 1¼" radius fits all valve rough-ins
- FIP Swivel Do NOT use pipe dope or teflon tape on FIP threads

Item No	Copper Type	CTS	Dim A	Dim B	No Lead
				MALE SWEAT	
613-107	L	1/2"	10"	7"	YES
613-139	L	1/2"	13"	9"	YES
613-57PK	L	1/2"	5"	7"	YES
613-67	L	1/2"	6"	7"	YES
613-137	L	1/2"	13"	7"	
613-57	L	1/2"	5"	7"	
613-87	L	1/2"	8"	7"	