



Detroit Speed
Billet Tailgate Handle Kit
1964-72 Ford F-100 & 1966-77 Ford Bronco
P/N: 012006DS

Detroit Speed's Billet Tailgate Handle will update the look and function of your classic truck tailgate. It is a direct factory replacement made with aluminum/stainless steel construction. Nylon pivot bushings will give your tailgate handle a smooth, quiet operation.



Item	012006DS - 64-72 Ford Truck, 66-77 Bronco	Part #	Quantity
1	Tailgate Handle	9303426	1
2	Tailgate Handle Hardware Bag - C/K	200178DS	1

Item	200178DS - 64-77 Ford Tailgate Hardware Bag	Part #	Quantity
1	FHCS, 1/4-20 x 1/2" Stainless	950157FS	2
2	Flanged Hex Nut, 1/4-20 Stainless	960122FS	2

Installation Instructions:

1. Remove the factory handle from tailgate. This requires removing the four screws on the located on the outside of the tailgate handle bezel, and two bolts on the inside of the tailgate.



Loosen & Remove Hardware

2. Pull the factory tailgate handle out of the tailgate. Remove the pins retaining the tailgate rods. Remove the rods from the tailgate handle and remove the handle.
NOTE: Insert a spacer to depress the tailgate latches to take tension off the tailgate rods before removing.



Remove Tailgate Handle

3. Place the DSE tailgate handle into the tailgate and re-install the tailgate rods into the DSE tailgate handle. Re-install the retaining pins into the tailgate rods



Install Tailgate Rods

4. Insert the 1/4"-20 x 1/2" L flat head screws through the tailgate handle and tailgate. Secure in place with the 1/4-20 flange hex nuts.
NOTE: apply anti-seize to the threads of the fastener



Figure 6 – Install Tailgate Handle

5. Align the handle to the tailgate and tighten fasteners



If you have any questions before or during the installation of this product, please contact Detroit Speed at tech@detroitsspeed.com or 704.662.3272

Legal Disclaimer: Detroit Speed is not liable for personal, property, legal, or financial damages from the use or misuse of any product we sell. The purchaser is solely responsible for the safety and performance of these products. No warranty is expressed or implied.