



Schematic- Piranha III Tungsten Grinder


Piranha Wiring
Diagram




SCHEMATIC - P-III 220VAC / 50 HZ



SCHEMATIC - P-III 220VAC / 60 HZ



SCHEMATIC - P-III 110VAC / 60 HZ



SCHEMATIC - P-III 110VAC / 50 HZ

SCHEMATICS - P-III ALL VOLTAGES/FREQUENCIES

REV	<Rev>
C	Document Number
001	0001
001	Wednesday, January 15, 2008 10:01 AM