MATERIAL SAFETY DATA SHEET

Lone Star Candle Supply, Inc. 5800 Park Vista Circle Keller, TX 76244

Ph: (817) 741-0876 Fax: (817) 741-0879 www.lonestarcandlesupply.com

Section I - Identification:

Product Name: Cranberry Kettle Corn Fragrance Oil
Product Code: SCENT-0433
Date Prepared: 8-21-13
Prepared By: Lone Star Candle Supply, Inc.

Section II - Product Information:

The specific chemical identities of the ingredients of this mixture are considered by Lone Star Candle Supply, Inc. to be trade secrets and are withheld in accordance with the provisions of 1910.1200 Title 29 of The Code of Federal Regulations.

Hazardous Ingredients:

Reportable Components	CAS Number	OSHA & ACGIH	NFPA
None			

This proprietary material contains the following toxic chemical(s) subject to the reporting requirements of Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 CFR Part 372.

Section III - Physical/Chemical Characteristics

Section 111 1 Hysical Chemical Characteristics			
Boiling Point (F): N/A	Specific Gravity (H20=1): ~ 1.104		
Vapor Density: N/A	Evaporation Rate: N/A		
Vapor Pressure (mm Hg): N/A	Solubility in Water: Insoluble		
Phys. Appearance & Odor: A LIGHT YELLO FRUITY TYPE ODOR.	OW TO YELLOW MOBILE LIQUID WITH A BERRY, SWEET,		

Section IV - Fire & Explosion Hazard Data

Flash Point (F): 200°F	Method: CCC			
Flammable Limits in Air by Volume - LOWER: N/A UPPER: N/A				
Extinguishing Media: Use Foam, Carbon Dioxide, Dry Chemical				
Special Firefighting Procedures: Self-contained apparatus & protective clothing should be worn when fighting fires involving chemicals. Cool exposed containers with water spray after extinguishing fire.				
Unusual Fire & Explosion Hazards: Closed containers may build pressure when exposed to heat or fire.				

Section V - Stability & Reactivity Data

Stability: Stable
Conditions to Avoid: Excessive Heat
Incompatibility (Materials to Avoid): Strong Oxidizing Agents
Hazardous Decomposition or Byproducts: Carbon Dioxide, Carbon Monoxide, Fumes
Hazardous Polymerization: Will not occur

Section VI - Health Hazard Data

Symptoms of Overexposure: Irritation to the eyes, mouth, nose, throat, skin, or respiratory system.

Health Hazards (Acute and Chronic): This product has not been tested as a whole.

Carcinogenicity - NTP Carcinogen: N/A IARC: Benzyl Acetate Not Classifiable as to Carcinogenicity in

Humans **OSHA**: Ethyl Oxydrate **ACGIH**: Ethyl Oxhydrate Animal Carcinogen

Medical Conditions Generally Aggravated by Exposure: None known to Lone Star Candle Supply, Inc.

EMERGENCY AND FIRST AID PROCEDURES

1. Inhalation: Seek fresh air immediately, if breathing is difficult, see physician.

- 2. Eyes: Flush immediately with clean water for at least 15 minutes. Contact physician as necessary.
- 3. Skin: Remove contaminated clothing. Wash affected areas with soap and water thoroughly.
- 4. Ingestion: Rinse mouth with water. Give water or milk to dilute. Contact physician immediately.

Section VII - Precautions for Safe Handling and Use

Steps to be taken in case material is released or spilled: Eliminate all ignition sources. Ventilate area. Absorb with suitable absorbent material. Use of self-contained breathing apparatus in recommended for major spills. Report major spills to appropriate authorities in required.

Waste Disposal Method: Place material & absorbent into a sealed container & dispose of in accordance with current applicable laws & regulations.

Precautions to be taken in handling and storing: Usual precautions for combustible liquids.

Other Precautions: Good manufacturing practices dictate that an eyewash fountain and/or safety shower should be available in the work area.

Section VIII - Control Measures

Respiratory Protection: None generally required. If desired, use NIOSH approved respirator.

Ventilation: Adequate Ventilation Required

Protective Gloves: Chemical resistant gloves

Eye Protection: Use splash goggles or face shield when eye contact may occur.

Other protective clothing or equipment: N/A

Work/Hygienic Practices: Good personal practices should be used. Wash after any contact. Contaminated clothing and shoes should be cleaned before reuse.

Section IX - Disclaimer

The information in this Material Safety Data Sheet was obtained from current and reliable sources however, the data is provided without any warranty, express or implied, regarding its correctness or accuracy. Since the conditions for use, handling, storage, and disposal of this product are beyond Lone Star Candle Supply, Inc.'s control, it is the responsibility of the user both to determine safe conditions for use of this product and to assume liability for loss, damage, or expense arising out of this product's improper use. Various federal, state, or provincial agencies may have specific regulations concerning the transportation, handling, storage, use, or disposal of this product which may not be reflected in this MSDS. The user shall review these regulations to ensure full compliance. No warranty express or implied regarding the product described herein shall be created by or inferred from any statement or omission in this Material Safety Data Sheet.